IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of: Confirmation No.: 1879

Amar GUETTAF

Patent. No.: 7,395,468 B2 Atty. Docket: 1875.4450000

Issued: July 1, 2008

For: Methods for Debugging Scan Testing

Failures of Integrated Circuits

Request for Certificate of Correction under 37 C.F.R. § 1.322

Attn: Certificate of Correction Branch

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

It is hereby requested that a Certificate of Correction under 37 C.F.R. § 1.322 and 1.323 be issued for the above-captioned United States Patent. This Certificate of Correction is being requested due to a mistakes which appear in the printed patent. This mistakes were made by the U.S. Patent and Trademark Office.

Specifically, the printed patent contains the following errors for which a Certificate of Correction is respectfully requested:

Column 11, line 17, "bad san paths" should be replaced with -- bad scan paths--.

Column 11, line 19, "Wherein" should be replaced with -- wherein--.

Column 11, line 38, "the path scan path" should be replaced with --the bad scan path--.

Support for the correction can be found in the Amendment filed December 27, 2007.

Amar GUETTAF Patent. No.: 7,395,468 B2 Atty. Docket: 1875.4450000

Remarks

The above-noted corrections do not involve such changes in the patent as would constitute new matter or would require reexamination.

A completed Form PTO/SB/44 accompanies this request, with the abovenoted correction printed thereon. Accordingly, a Certificate of Correction is believed proper and issuance thereof is respectfully requested.

The Commissioner is hereby authorized to charge any fee deficiency, or credit any overpayment, to our Deposit Account No. 19-0036.

Respectfully submitted,

STERNE, KESSLER, GOLDSTEIN & FOX P.L.L.C.

Michael D. Specht Attorney for Patentee Registration No. 54,463

Date: 29 08 1100 New York Avenue, N.W. Washington, D.C. 20005-3934 (202) 371-2600

891534_1.DOC

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,395,468 B2

DATED

July 1, 2008

INVENTOR(S) :

Amar GUETTAF

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 11, line 17, "bad san paths" should be replaced with --bad scan paths--.

Column 11, line 19, "Wherein" should be replaced with --wherein--.

Column 11, line 38, "the path scan path" should be replaced with -- the bad scan path--.

MAILING ADDRESS OF SENDER:

PATENT NO.

7,395,468 B2

Sterne, Kessler, Goldstein & Fox P.L.L.C. 1100 New York Avenue, N.W.

No. of additional copies

Washington, DC 20005-3934

0

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.